

Approved Organization Certificate

Yuri Hoverson
General Manager
Able Aerospace Services, Inc.

The under-mentioned organization is approved pursuant to Article 20, Paragraph 1 of Civil Aeronautics Law.

1. Approved Organization

Able Aerospace Services, Inc.

2. Address

7706 East Velocity Way Mesa, AZ 85212, USA

3. Category

Capabilities to perform repair or alteration on components

4. Rating

Services pertaining to rotors, Service pertaining to transmissions, Services pertaining to engine accessories, Service pertaining to components etc. of landing systems, Service pertaining to components etc. of hydraulic systems, Service pertaining to components etc. of air conditioning or pressurized systems, Service pertaining to components etc. of electrical systems, Service pertaining to components etc. of flight control

5. Limitation

As listed on the appendix

6. Validity Period

From December 11, 2025 to December 10, 2027

Date Issued : December 2, 2025

KANEKO Yasushi

Minister of Land, Infrastructure, Transport and Tourism

Note: This is a translation of approved organization certificate issued by Japanese Minister of Land, Infrastructure, Transport and Tourism and shall not be construed as an official text.

• Limitation by kind and type of the components

Scope of ratings: Services pertaining to rotors

Kind of the components	Type of the components
Main Rotor Hub Assembly	204-011-326-(), 204-011-401-(), 204-012-101-(), 206-010-100-(), 206-010-360-(), 206-011-100-(), 206-011-117-(), 206-040-513-(), 209-011-712-(), 222-010-400-(), 222-040-002-(), 406-010-100-(), 406-010-401-(), 406-010-413-(), 406-010-427-(), 406-010-428-(), 407-010-100-(), 407-010-152-(), 407-010-206-(), 412-010-100-(), 412-010-190-(), 412-010-401-(), 412-010-402-(), 412-010-425-(), 412-018-060-(), 412-040-366-(), 429-110-100-(), 350A31-1770-(), 350A31-1831-(), 350A31-1877-(), 350A31-2019-(), 355A35-2001-(), 355A35-2003-(), 366A31-0006-(), 105-13122-(), 105-13221-(), 105-14101-(), 105-14181-(), 550655-(), 109-0111-07-(), 109-0134-09-(), 3G6220A00132-(), 3G6220A00134-(), 3G6220A00332-(), 3G6220A00531-(), 3G6220A00732-(), 3G6230A01032-(), 3G6230A01033-(), 3G6230A00232-(), 3G6320A00233-(), 3G6320A00234-(), 3G6330A00532-(), 3G6330A00552-(), 76104-08011-(), 76106-08000-(), 782500-1-()
Main Rotor Hub and Sleeve Assembly	204-011-401-(), 412-010-401-()
Swashplate Assembly	204-011-400-(), 204-011-401-(), 206-010-450-(), 206-010-800-(), 406-010-401-(), 406-010-402-(), 412-010-401-(), 412-010-402-(), 429-010-400-(), 350A12-1368-(), 350A33-2119-(), 350A33-2121-(), 350A33-2145-(), 350A37-1004-(), 350A37-1181-(), 366A31-0006-(), 105-31729-(), 105-317318-(), B623M4005101-(), 3G6230A00132-(), 3G6230A00732-(), 3G6230A00733-(), 76104-08011-()
Tail Rotor Hub Assembly	204-011-801-(), 206-011-749-(), 206-011-810-(), 206-011-814-(), 209-011-710-(), 209-011-713-(), 212-010-706-(), 212-010-775-(), 212-011-700-(), 212-011-701-(), 222-012-701-(), 222-042-001-(), 407-012-101-(), 429-012-101-(), 350A33-2030-()

Scope of ratings: Services pertaining to transmissions

Kind of the components	Type of the components
Main Transmission Assembly	204-040-009-(), 204-040-016-(), 204-040-102-(), 204-040-270-(), 204-040-306-(), 204-040-314-(), 204-040-353-(), 204-040-362-(), 204-040-379-(), 204-040-399-(), 204-040-700-(), 205-040-001-(), 205-040-125-(), 205-040-233-(), 205-040-263-(), 205-040-300-(), 205-040-784-(), 206-040-002-(), 206-040-004-(), 206-040-033-(), 206-040-037-(), 206-040-038-(), 206-040-091-(), 206-040-192-(), 206-040-400-(), 206-040-532-(), 206-040-540-(), 212-040-001-(), 212-040-003-(), 212-040-154-(), 212-040-208-(), 212-040-365-(), 212-540-002-(), 214-001-301-(), 214-040-659-(), 222-012-701-(), 222-040-003-(), 406-040-007-(), 406-040-028-(), 406-040-530-(), 406-360-500-(), 407-010-201-(), 407-010-203-(), 407-040-006-(), 407-040-007-(), 407-040-011-(), 407-340-032-(), 412-040-002-(), 412-040-004-(), 412-040-005-(), 412-040-007-(), 412-040-121-(), 412-040-123-(), 412-040-263-(), 412-040-302-(), 412-706-029-(), 429-040-006-(), 429-040-201-(), 430-040-003-(), 350A32-3088-(), 350A32-3119-(), 350A32-3121-(), 350A32-3156-(), 350A35-1093-(), 350A35-1102-(), 350A35-1105-(), 350A38-1018-(), 365A32-3046-(), 365A32-7108-(), 366A31-0006-(), 4639-205-007-(), 3G6330A00111-(), 3G6330A00112-(), 3G6330A00311-(), 3G6330A00232-(), 3G6330L00131-(), 3G6330L00132-(), 3G6330L00231-(), 3G6330L00232-(), 3G6330V00131-(), 3G6330V00231-(), DPN63020-(), 76351-09500-()
Tail Gearbox Assembly	204-040-003-(), 206-011-721-(), 206-040-400-(), 206-040-402-(), 206-040-405-(), 206-961-401-(), 212-040-004-(), 212-040-365-(), 406-012-108-(), 406-012-118-(), 406-040-400-(), 412-040-620-(), 412-040-612-(), 412-706-029-(), 429-042-001-(), 429-044-100-(), 429-044-250-(), 350A33-1058-(), 350A33-1092-(), 350A33-1526-(), 105-317261-(), 105-31765-(), 105-31782-(), 105-31802-(), 1121-31721-(), 117-31821-(), 4639-211-001-(), 3G6320A00132-(), 3G6320A00133-(), 3G6320A00134-(), 3G6320A00135-(), 3G6320A00952-(), 76102-05001-(), 76358-05109-()
42 Degree Gearbox Assembly	204-040-600-(), 212-040-003-(), 212-040-004-(), 212-040-365-(), 212-040-600-(), 412-040-006-(), 412-706-029-()

Note: This is a translation of approved organization certificate issued by Japanese Minister of Land, Infrastructure, Transport and Tourism and shall not be construed as an official text.

- Limitation by kind of the components

Scope of ratings	Kind of the components
Services pertaining to engine accessories	Engine Mount
Service pertaining to components etc. of landing systems	Landing Gear
Service pertaining to components etc. of hydraulic systems	Hydraulic Pump, Hydraulic Reservoir, Flight Control Actuator
Service pertaining to components etc. of air conditioning or pressurized systems	A/C Compressor
Service pertaining to components etc. of electrical systems	Wiper Motor Assembly, Generator, Starter-Generator
Service pertaining to components etc. of flight control	Main Rotor Mast Assembly, Main Drive Shaft Assembly, Tail Rotor Drive Shaft Assembly, Coupling Assembly, Transmission Mount, Flight Control System, Elevator, Freewheeling Unit, Oil Pump, Oil Cooler Blower, Brake Assembly, Rotor Brake Master Cylinder Assembly, Rotor Brake Assembly, Lift Link

- Limitation by classification of work: Repair and Alteration

Note: This is a translation of approved organization certificate issued by Japanese Minister of Land, Infrastructure, Transport and Tourism and shall not be construed as an official text.